

Standard Of Performance Data for the month of June-2020

Name of Transmission Licensee : POWER GRID CORPORATION OF INDIA LTD.

Region: NORTH EASTERN REGION TRANSMISSION SYSTEM

ANNEXURE-A

Unique ID of transmission Element	Element Name		Description (Length/No./MVA/MVAr/MWetc.)	Region	Type of failure	OUTAGE		RESTORATION		Details of Outage		Total outage in days (1)	DURATION OF OUTAGE ATTRIBUTABLE TO (in Hrs)						Restoration Time as per Regulation 5(b) (2)	Whether Restoration Time more than normative	Difference between Actual and Norm 1:2	Detailed Reason(s) for Outage	Outage Certifying Agency and Reference Document	% Availability as certified by certifying agency			
						Date	Time	Date	Time	No. of towers damaged	no. of insulator failed		ISTS License Hr	min	OTHERS Hr	min	System Constraints/ Natural calamity / Mibitancy Hr	min								Decreed Available Hr	min
NER L156	AIZAWL - TIPAIMUKH	#1	95.6			10/06/20	14:35	10/06/20	14:46				0	11	0	0	0	0	0	0	0		BURNING SPOTS FOUND IN ARCING HORN OF R-PH CONDUCTOR AT LOC 407 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	99.97	OMST	
						Sub Total -->							0	11	0	0	0	0	0	0	0						
NER L152	AIZAWL MELRIAT		6.654			29/06/20	09:03	29/06/20	09:23				0	20	0	0	0	0	0	0	0		UNWANTED OPERATION OF E/F RELAY AT AIZAWL FOR SOME DISTANCE FAULT	NERPC/OP/TAC/2 0-21/443	99.95	SRMT	
						Sub Total -->							0	20	0	0	0	0	0	0	0						
NER L104	AIZWAL_KUMARGHAT		131			09/06/20	19:08	09/06/20	19:17				0	0	0	0	0	0	9	0	0		FLASHOVER MARK AT B-PH TOP INSULATOR ARCING HORN AT LOC 237 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	100	LNCC	
						Sub Total -->							0	0	0	0	0	0	9	0	0						
NER L145	AIZWAL-KOLASIB		66.098			11/06/20	00:40	11/06/20	01:00				0	20	0	0	0	0	0	0	0		FLASHOVER MARK FOUND ON ARCING HORN OF R & Y PH AT LOC 180 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	100	OMST	
						Sub Total -->							0	20	0	0	0	0	0	0	0						
NER L419	B.CHAIRALI_RANGANADI #1		131.03		x	x	x	x	x			x	x	x	x	x	x	x	x	x	x	x			100	x	
						Sub Total -->							x	x	x	x	x	x	x	x	x	x					
NER L420	B.CHAIRALI_RANGANADI #2		131.03			10/06/20	08:47	10/06/20	13:54				0	0	5	7	0	0	0	0	0		SD TAKEN BY RANGANADI	NERPC/OP/TAC/2 0-21/443	100	OMSU	
						Sub Total -->							0	0	5	7	0	0	0	0	0	0					
NER L142	B.CHARAILI_PAVOI #1		12.931			28/06/20	06:01	28/06/20	10:35				0	0	0	0	0	0	4	34		132KV MAIN BUS SD TAKEN AT BNC FOR TERMINATION OF NEW 132KV BUS TO EXISTING BUS UNDER NERSS VI	NERPC/OP/TAC/2 0-21/443	100	SCSD		
						Sub Total -->							0	0	0	0	0	0	4	34							
NER L143	B.CHARAILI_PAVOI #2		12.931			28/06/20	06:01	28/06/20	10:35				0	0	0	0	0	0	4	34		132KV MAIN BUS SD TAKEN AT BNC FOR TERMINATION OF NEW 132KV BUS TO EXISTING BUS UNDER NERSS VI	NERPC/OP/TAC/2 0-21/443	100	SCSD		
						Sub Total -->							0	0	0	0	0	0	4	34							
NER L107	BADARPUR_JIRIBAM		67.21		x	x	x	x	x			x	x	x	x	x	x	x	x	x	x	x			100	x	
						Sub Total -->							x	x	x	x	x	x	x	x	x	x					
NER L108	BADARPUR_KHLIERIAT		76.646			03/06/20	01:42	03/06/20	01:47				0	5	0	0	0	0	0	0	0		CC RING OF ALL 3 PHASES OF POLYMER INSULATOR STRING FOUND DAMAGED AT LOC 181 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	99.99	OMST	
NER L108	BADARPUR_KHLIERIAT		76.646			06/06/20	05:54	06/06/20	06:15				0	0	0	21	0	0	0	0	0		TRIPPED DUE TO FAULT IN 132KV KHLIEHRIAT-LUMSHONG WHICH WAS NEITHER CLEARED AT KHLIEHRIAT (STATE)			OMSU	
						Sub Total -->							0	5	0	21	0	0	0	0	0						
NER L103	BADARPUR_KOLASIB		107.226			02/06/20	06:10	02/06/20	06:25				0	15	0	0	0	0	0	0	0		BURNING MARKS FOUND IN B-PH ARCING HORN AT LOC 46 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	99.96	OMST	
NER L103	BADARPUR_KOLASIB		107.226			11/06/20	14:59	11/06/20	15:29				0	0	0	30	0	0	0	0	0		TRIPPED FOR AIZAWL-KOLASIB LINE FAULT			OMSU	
NER L103	BADARPUR_KOLASIB		107.226			12/06/20	11:26	12/06/20	14:48				0	0	0	0	3	22	0	0	0		E/S/D TAKEN FOR CLEARING OF BAMBOOS WHICH CAME NEAR TO THE CONDUCTORS FROM OUTSIDE CORRIDOR	NERPC/OP/TAC/2 0-21/443		LNCC	
NER L103	BADARPUR_KOLASIB		107.226			24/06/20	11:52	24/06/20	18:44				0	0	0	0	0	0	6	52		ESD TAKEN TO REPLACE ZIV MAKE DP RELAY BY MICOM P442 RELAY	NERPC/OP/TAC/2 0-21/443	SCSD			
						Sub Total -->							0	15	0	30	3	22	6	52							
NER L109	BADARPUR_KUMARGHAT		118.513			17/06/20	16:48	17/06/20	17:54				0	0	0	0	1	6	0	0	0		E/S/D TAKEN FOR CLEARING A BETEL NUT TREE BETWEEN LOC. NO. 47-48 DUE LANDSLIDE.	NERPC/OP/TAC/2 0-21/443	100	LNCC	
						Sub Total -->							0	0	0	0	1	6	0	0	0						

Unique ID of transmission Element	Element Name	Description (Length/No./MVA/MVA/RMW/etc.)	Region	Type of failure	OUTAGE		RESTORATION		Details of Outage		Total outage in days (1)	DURATION OF OUTAGE ATTRIBUTABLE TO (in Hrs)						Restoration Time as per Regulation 5(b) (2)	Whether Restoration Time more than normative	Difference between Actual and Norm 1-2	Detailed Reason(s) for Outage	Outage Certifying Agency and Reference Document	% Availability as certified by certifying agency						
					Date	Time	Date	Time	No. of towers damaged	no. of insulator failed		ISTS License Hr	min	OTHERS Hr	min	System Constraints/ Natural calamity / MIBitancy Hr	min								Demed Available Hr	min			
NER L106	BADARPUR-BADARPUR	1			01/06/20	11:14	01/06/20	15:47				4	33	0	0	0	0	0	0								OSPT		
NER L106	BADARPUR-BADARPUR	1			27/06/20	10:42	27/06/20	13:31				2	49	0	0	0	0	0	0								OMST		
Sub Total -->											7	22	0	0	0	0	0	0											
NER L421	BALIPARA_B.CHAIRALI#1	59.995		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L422	BALIPARA_B.CHAIRALI	#2	59.995		07/06/20	09:56	07/06/20	17:24				7	28	0	0	0	0	0	0								OMST		
NER L422	BALIPARA_B.CHAIRALI	#2	59.995		24/06/20	10:36	24/06/20	19:05				0	0	0	0	0	0	8	29								SCSD		
Sub Total -->											7	28	0	0	0	0	8	29											
NER L417	BALIPARA_B.CHAIRALI#3	57.294		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L418	BALIPARA_B.CHAIRALI#4	57.294		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L401	BALIPARA_BONGAIGAON	#1	289.721		20/06/20	10:17	20/06/20	16:42				0	0	0	0	0	0	6	25								100	SCSD	
Sub Total -->											0	0	0	0	0	0	6	25											
NER L402	BALIPARA_BONGAIGAON	#2	289.721		01/06/20	11:38	01/06/20	21:32				0	0	0	0	0	0	9	54								100	LVRD	
Sub Total -->											0	0	0	0	0	0	9	54											
NER L201	BALIPARA_SONABIL	8.623		CONDUCT	16/06/20	18:41	17/06/20	19:32				24	51	0	0	0	0	0	0									96.55	LHWT
Sub Total -->											24	51	0	0	0	0	0	0											
NER L413	BALIPARA-BONGAIGAON	#3	309		01/06/20	22:47	05/06/20	19:21				0	0	0	0	0	0	92	34								99.73	LVRD	
NER L413	BALIPARA-BONGAIGAON	#3	309		16/06/20	03:05	16/06/20	05:01				1	56	0	0	0	0	0	0									SEMT	
Sub Total -->											1	56	0	0	0	0	92	0											
NER L414	BALIPARA-BONGAIGAON	#4	309		01/06/20	00:00	01/06/20	11:38				0	0	0	0	0	0	11	38								100	LVRD	
Sub Total -->											0	0	0	0	0	0	11	38											
NER L429	BALIPARA-KAMENG#1	57.2		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L430	BALIPARA-KAMENG#2	57.2		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L407	BALIPARA-RANGANADI#1	166.335		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L408	BALIPARA-RANGANADI#2	166.335		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L220	BONGAIGAON_SALAKATI #1	0.5		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L221	BONGAIGAON_SALAKATI #2	0.5		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L411	BTBS-BONGAIGAON	#1	3.119		09/06/20	11:44	09/06/20	12:56				0	0	1	12	0	0	0	0								100	OMSU	
Sub Total -->											0	0	1	12	0	0	0	0											
NER L412	BTBS-BONGAIGAON#2	3.119		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L132	DIMAPUR(PG)-DIMAPUR(LILO PORTION)	0.347		x	x	x	x				x	x	x	x	x	x	x	x									100	x	
Sub Total -->																													
NER L131	DIMAPUR(PG)-KOHIMA(LILO PORTION)	0.347			20/06/20	11:33	20/06/20	11:54				0	0	0	21	0	0	0	0									OMSU	
NER L131	DIMAPUR(PG)-KOHIMA(LILO PORTION)	0.347			22/06/20	08:42	22/06/20	11:54				0	0	3	12	0	0	0	0								100	OMSU	
Sub Total -->											0	0	3	33	0	0	0	0											

Unique ID of transmission Element	Element Name	Description (Length/No./MVA/MVAR/MW/etc.)	Region	Type of failure	OUTAGE		RESTORATION		Details of Outage		Total outage in days (1)	DURATION OF OUTAGE ATTRIBUTABLE TO (in Hrs)				Restoration Time as per Regulation 5(b) (2)	Whether Restoration Time more than normative	Difference between Actual and Norm 1-2	Detailed Reason(s) for Outage	Outage Certifying Agency and Reference Document	% Availability as certified by certifying agency		
					Date	Time	Date	Time	No. of towers damaged	no. of insulator failed		ISTS License Hr	min	OTHERS Hr	min								System Constraints/ Natural calamity / Mbitancy Hr
NER L110	DIMAPUR_IMPHAL	168.865			01/06/20	00:00	30/06/20	23:59				0	0	0	0	719	59	0	0	LIME PU TUNDR CONTINUOUS SD TO FACILITATE NH DIVERSION (EXPANSION) WORK AT REQUEST OF STATE ADMIN.	NERPC/OP/TAC/2 0-21/443	100	LNCC
					Sub Total -->							0	0	0	0	719	59	0	0				
NER L111	DOYANG_DIMAPUR	# 1 92.526			17/06/20	13:51	17/06/20	15:06				1	15	0	0	0	0	0	0	TRIPPED DUE TO LIGHTNING.	NERPC/OP/TAC/2 0-21/443	99.83	OMST
					Sub Total -->							1	15	0	0	0	0	0	0				
NER L112	DOYANG_DIMAPUR# 2	92.526			x	x	x	x				x	x	x	x	x	x	x	x		NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x		NERPC/OP/TAC/2 0-21/443	100	x
NER L113	GOHPUR_NIRJULI	42.5			x	x	x	x				x	x	x	x	x	x	x	x		NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x		NERPC/OP/TAC/2 0-21/443	100	x
NER L147	HAFLONG-UMRANGSO	55.485			11/06/20	13:01	11/06/20	16:18				3	17	0	0	0	0	0	0	E/S/D TAKEN TO FACILITATE BUS S/D AT HAFLONG (POWERGRID) TO ATTEND SPARKING	NERPC/OP/TAC/2 0-21/443		OMST
NER L147	HAFLONG-UMRANGSO	55.485			15/06/20	08:31	15/06/20	18:59				0	0	10	28	0	0	0	0	SHUT DOWN TAKEN BY STERLITE			OMSU
NER L147	HAFLONG-UMRANGSO	55.485			16/06/20	07:58	16/06/20	17:54				0	0	9	56	0	0	0	0	SHUT DOWN TAKEN BY STERLITE			OMSU
NER L147	HAFLONG-UMRANGSO	55.485			26/06/20	15:58	27/06/20	13:48				0	0	0	0	21	50	0	0	A BIG TREE FROM OUTSIDE LIEN CORRIDOR FELL ON B-PH CONDUCTOR AT LOC 53-54	NERPC/OP/TAC/2 0-21/443		LNCC
					Sub Total -->							3	17	20	24	21	50	0	0				
NER L114	IMPHAL_IMPHAL	#1 1.5			08/06/20	11:49	08/06/20	11:55				0	0	0	6	0	0	0	0	TRIPPED DUE TO DOWNSTREAM FAULT	NERPC/OP/TAC/2 0-21/443		OMSU
NER L114	IMPHAL_IMPHAL	#1 1.5			08/06/20	13:35	08/06/20	13:44				0	0	0	9	0	0	0	0	TRIPPED DUE TO DOWNSTREAM FAULT	NERPC/OP/TAC/2 0-21/443	100	OMSU
NER L114	IMPHAL_IMPHAL	#1 1.5			25/06/20	15:27	25/06/20	16:28				0	0	1	1	0	0	0	0	ESD TAKEN BY STATE	NERPC/OP/TAC/2 0-21/443		OMSU
					Sub Total -->							0	0	1	16	0	0	0	0		NERPC/OP/TAC/2 0-21/443		
NER L137	IMPHAL-IMPHAL	# 2 0.442			08/06/20	11:49	08/06/20	12:01				0	0	0	12	0	0	0	0	TRIPPED DUE TO DOWNSTREAM FAULT	NERPC/OP/TAC/2 0-21/443		OMSU
NER L137	IMPHAL-IMPHAL	# 2 0.442			08/06/20	13:35	08/06/20	13:44				0	0	0	9	0	0	0	0	TRIPPED DUE TO DOWNSTREAM FAULT	NERPC/OP/TAC/2 0-21/443		OMSU
NER L137	IMPHAL-IMPHAL	# 2 0.442			10/06/20	11:26	10/06/20	11:43				0	0	0	17	0	0	0	0	TRIPPED DUE TO FAULT IN 132KV IMPHAL-YANKANGOKPI (STATE FEEDER)	NERPC/OP/TAC/2 0-21/443	100	OMSU
NER L137	IMPHAL-IMPHAL	# 2 0.442			20/06/20	14:06	20/06/20	14:24				0	0	0	18	0	0	0	0	TRIPPED FOR FAULT IN 132KV IMPHAL-KARONG STATE LINE	NERPC/OP/TAC/2 0-21/443		OMSU
NER L137	IMPHAL-IMPHAL	# 2 0.442			30/06/20	14:25	30/06/20	15:05				0	0	0	40	0	0	0	0	SHUT DOWN TAKEN BY STATE	NERPC/OP/TAC/2 0-21/443		OMSU
					Sub Total -->							0	0	1	36	0	0	0	0		NERPC/OP/TAC/2 0-21/443		
NER L157	JIRIBAM - TIPAIMUKH#1	76.786			x	x	x	x				x	x	x	x	x	x	x	x		NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x		NERPC/OP/TAC/2 0-21/443	100	x
NER L116	JIRIBAM_HAFLONG	100.63			11/06/20	13:02	11/06/20	16:08				3	6	0	0	0	0	0	0	E/S/D TAKEN TO FACILITATE BUS S/D AT HAFLONG (POWERGRID) TO ATTEND SPARKING	NERPC/OP/TAC/2 0-21/443		OMST
NER L116	JIRIBAM_HAFLONG	100.63			26/06/20	15:58	26/06/20	16:22				0	24	0	0	0	0	0	0	TRIPPED DUE TO TRANSIENT FAULT	NERPC/OP/TAC/2 0-21/443	99.5	OMST
NER L116	JIRIBAM_HAFLONG	100.63			26/06/20	16:49	26/06/20	16:55				0	6	0	0	0	0	0	0	TRIPPED DUE TO TRANSIENT FAULT	NERPC/OP/TAC/2 0-21/443		OMST
					Sub Total -->							3	36	0	0	0	0	0	0				
NER L117	JIRIBAM_LOKTAK	# 2 82.4			27/06/20	10:13	27/06/20	17:08				0	0	0	0	0	0	6	55	SD TAKEN FOR OPGW STRINGING IN 132KV JBM-LKT & 132KV LKT-RENGPANG SIMULTANEOUSLY	NERPC/OP/TAC/2 0-21/443		LCSD
NER L117	JIRIBAM_LOKTAK	# 2 82.4			28/06/20	10:48	28/06/20	16:38				0	0	0	0	0	0	5	50	SD TAKEN FOR OPGW STRINGING IN 132KV LOKTAK-JIRIBAM & 132KV LOKTAK-RENGPANG	NERPC/OP/TAC/2 0-21/443	100	LCSD
NER L117	JIRIBAM_LOKTAK	# 2 82.4			29/06/20	08:59	29/06/20	15:54				0	0	0	0	0	0	6	55	S/D TAKEN FOR OPGW STRINGING IN 132 KV LOKTAK-JIRIBAM AND 132 KV LOKTAK-RENGPANG SIMULTANEOUSLY	NERPC/OP/TAC/2 0-21/443		LCSD
					Sub Total -->							0	0	0	0	0	0	19	40				
NER L202	KATHALGURI_MARIANI(OLD)	162.864			09/06/20	12:58	09/06/20	15:02				0	0	2	4	0	0	0	0	TRIPPED DUE TO UNDESIRABLE LBB OPERATION	NERPC/OP/TAC/2 0-21/443	100	OMSU

Unique ID of transmission Element	Element Name	Description (Length/No./MVA/MVA/MW/etc.)	Region	Type of failure	OUTAGE		RESTORATION		Details of Outage		Total outage in days (1)	DURATION OF OUTAGE ATTRIBUTABLE TO (in Hrs)						Restoration Time as per Regulation 5(b) (2)	Whether Restoration Time more than normative	Difference between Actual and Norm 1-2	Detailed Reason(s) for Outage	Outage Certifying Agency and Reference Document	% Availability as certified by certifying agency		
					Date	Time	Date	Time	No. of towers damaged	no. of insulator failed		ISTS License Hr	OTHERS Hr	System Constraints/ Natural calamity / Mbitancy Hr		Deemed Available min									
					Sub Total -->							0	0	2	4	0	0	0	0						
NER L215	KATHALGURI-MARIANI(NEW)	160.536			09/06/20	12:58	09/06/20	15:22				0	0	2	24	0	0	0	0			TRIPPED DUE TO UNDESIRABLE LBB OPERATION AT KATHALGURI	NERPC/OP/TAC/2 0-21/443	100	OMSU
					Sub Total -->							0	0	2	24	0	0	0	0						
NER L120	KHANDONG_KHLIERIAT# 2	40.933		x	x	x	x				x	x	x	x	x	x	x	x			x	NERPC/OP/TAC/2 0-21/443		x	
					Sub Total -->							0	21	0	0	0	0	0	0			TRIPPE DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	100	OMST
NER L119	KHANDONG_KHLIERIAT	42.48			27/06/20	21:25	27/06/20	21:46				0	21	0	0	0	0	0	0						
					Sub Total -->							0	21	0	0	0	0	0	0						
NER L121	KHANDONG_KOPILI # 1	10.914			01/06/20	00:00	30/06/20	23:59				0	0	0	0	0	0	719	59			SD TAKEN FOR DISMANTLING EXISTING BAY EQUIPMENTS TO INTEGRATE THROUGH GIS.	NERPC/OP/TAC/2 0-21/443	99.95	SCSD
					Sub Total -->							0	0	0	0	0	0	719	59					100	
NER L130	KHANDONG_KOPILI # 2	11.56			01/06/20	00:00	30/06/20	23:59				0	0	719	59	0	0	0	0			LINE PUT UNDER SD DUE TO RUPTURE OF PEMSTOCK NO 1	NERPC/OP/TAC/2 0-21/443		OMSU
					Sub Total -->							0	0	719	59	0	0	0	0					100	
NER L118	KHANDONG-HAFLONG	63.166		x	x	x	x				x	x	x	x	x	x	x	x			x	NERPC/OP/TAC/2 0-21/443		x	
					Sub Total -->							x	x	x	x	x	x	x	x					100	x
NER L150	KHANDONG-KOPILI#2	11.56		x	x	x	x				x	x	x	x	x	x	x	x			x	NERPC/OP/TAC/2 0-21/443		x	
					Sub Total -->							0	0	1	2	0	0	0	0					100	
NER L149	KHANDONG-UMRANGSO	14.4			26/06/20	15:58	26/06/20	17:00				0	0	1	2	0	0	0	0			TRIPPED DUE TO DOWNSTREAM FAULT	NERPC/OP/TAC/2 0-21/443	100	OMSU
					Sub Total -->							0	0	1	2	0	0	0	0					100	
NER L122	KHLIERIAT_KHLIERIAT	7.801			29/06/20	12:30	29/06/20	14:47				2	17	0	0	0	0	0	0			E/S/D TAKEN BY KHLIERIAT (PG) FOR ATTENDING HOTSPOT IN R-PH CT CONNECTOR	NERPC/OP/TAC/2 0-21/443	99.68	OMST
					Sub Total -->							2	17	0	0	0	0	0	0						
NER L128	KOLASIB-AIZAWL	66.098			11/06/20	14:59	11/06/20	15:25				0	26	0	0	0	0	0	0			FLASHOVER MARK FOUND ON ARCING HORN OF R PH AT LOC 164 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443		OMST
NER L128	KOLASIB-AIZAWL	66.098			20/06/20	18:54	20/06/20	18:57				0	2	0	0	0	0	0	0			FLASHOVER MARK FOUND IN ARCING HORN OF R-PH CONDUCTOR AT LOC 145	NERPC/OP/TAC/2 0-21/443	99.01	OMST
NER L128	KOLASIB-AIZAWL	66.098			22/06/20	11:51	22/06/20	17:52				6	1	0	0	0	0	0	0			EMERGENCY S/D TAKEN FOR RELAY RETROFICATION AT KOLASIB END.	NERPC/OP/TAC/2 0-21/443		OMST
NER L128	KOLASIB-AIZAWL	66.098			22/06/20	17:52	23/06/20	20:46				0	0	0	0	26	54	0	0			ESD FOR RELAY RETROFITTING. SIMULTANEOUSLY TREE FELL BY MISCREANTS BETWEEN LOC 192-193	NERPC/OP/TAC/2 0-21/443		LMAC
					Sub Total -->							6	29	0	0	26	54	0	0						
NER L123	KUMARGHAT_R C NAGAR	104.02			10/06/20	02:29	10/06/20	02:39				0	10	0	0	0	0	0	0			DISC INSULATOR FOUND BROKEN IN B-PH INSULATOR AT LOC 231 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	99.95	OMST
NER L123	KUMARGHAT_R C NAGAR	104.02			10/06/20	03:41	10/06/20	03:52				0	11	0	0	0	0	0	0			DISC INSULATOR FOUND BROKEN IN B-PH INSULATOR AT LOC 231 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443		OMST
NER L123	KUMARGHAT_R C NAGAR	104.02			25/06/20	09:22	26/06/20	18:03				0	0	32	41	0	0	0	0			SD TKAEN BY STERLITE	NERPC/OP/TAC/2 0-21/443		OMSU
					Sub Total -->							0	21	32	41	0	0	0	0						
NER L154	LEKHI(LILO)_PARE(LILO)	10			10/06/20	10:50	10/06/20	11:30				0	0	0	40	0	0	0	0			TRIPPED DUE TO FAULT IN 132KV RANGANADI-CHIMPU STATE FEEDER	NERPC/OP/TAC/2 0-21/443	100	OMSU
NER L154	LEKHI(LILO)_PARE(LILO)	10			28/06/20	12:02	28/06/20	13:57				0	0	1	55	0	0	0	0			LINE H/T TO FACILITATE E/S/D AT LEKHI SS	NERPC/OP/TAC/2 0-21/443		OMSU
					Sub Total -->							0	0	2	35	0	0	0	0						
NER L124	LOKTAK_IMPHAL# 2	35.04		x	x	x	x				x	x	x	x	x	x	x	x			x	NERPC/OP/TAC/2 0-21/443		x	
					Sub Total -->																			100	
NER L216	MARIANI_MOKUKCHUNG #1	48.8			05/06/20	16:55	05/06/20	19:58				3	3	0	0	0	0	0	0			LINE OUT AS IT IS CHARGED THROUGH BUS REACTOR BAY	NERPC/OP/TAC/2 0-21/443	99.58	OSFT
					Sub Total -->							3	3	0	0	0	0	0	0						
NER L217	MARIANI_MOKUKCHUNG #2	48.8		x	x	x	x				x	x	x	x	x	x	x	x			x	NERPC/OP/TAC/2 0-21/443		x	
					Sub Total -->							x	x	x	x	x	x	x	x					100	x
NER L153	MELRIAT - ZEMABAWK	10.7		x	x	x	x				x	x	x	x	x	x	x	x			x	NERPC/OP/TAC/2 0-21/443		x	
					Sub Total -->							x	x	x	x	x	x	x	x					100	x

Unique ID of transmission Element	Element Name	Description (Length/No./MVA/MVA/MW/etc.)	Region	Type of failure	OUTAGE		RESTORATION		Details of Outage		Total outage in days (1)	DURATION OF OUTAGE ATTRIBUTABLE TO (in Hrs)						Restoration Time as per Regulation 5(b) (2)	Whether Restoration Time more than normative	Difference between Actual and Norm 1-2	Detailed Reason(s) for Outage	Outage Certifying Agency and Reference Document	% Availability as certified by certifying agency	
					Date	Time	Date	Time	No. of towers damaged	no. of insulator failed		ISTS License Hr	min	OTHERS Hr	min	System Constraints/ Natural calamity / Mbitancy Hr	min							
NER L403	MISA_BALIPARA# 1	95.407			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443		x	
					Sub Total -->																NERPC/OP/TAC/2 0-21/443	100	x	
NER L203	MISA_DIMAPUR# 1	123.52			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443		x	
					Sub Total -->																NERPC/OP/TAC/2 0-21/443	100	x	
NER L204	MISA_DIMAPUR# 2	123.52			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443		x	
					Sub Total -->																NERPC/OP/TAC/2 0-21/443	100	x	
NER L205	MISA_KATHALGURI	382.864			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443		x	
					Sub Total -->																	0-21/443	100	x
NER L207	MISA_KOPILI # 2	72.791			01/06/20	00:00	30/06/20	23:59			0	0	719	59	0	0	0	0			LINE H/T WIDE CODE 3783 AS PER ISNTRUCTION OF NERLDC AFTER PENSTOCK RUPTURE AT KOPILI HEP.	NERPC/OP/TAC/2 0-21/443	100	OMSU
					Sub Total -->						0	0	719	59	0	0	0	0				0-21/443	100	OMSU
NER L208	MISA_KOPILI # 3	75.788			01/06/20	00:00	30/06/20	23:59			0	0	719	59	0	0	0	0			LINE H/T WIDE CODE 3783 AS PER NERLDC ISNTRUCTION AFTER PENSTOCK RUPTURE	NERPC/OP/TAC/2 0-21/443	100	OMSU
					Sub Total -->						0	0	719	59	0	0	0	0				0-21/443	100	OSPT
NER L209	MISA_MARIANI(OLD)	220			03/06/20	09:24	03/06/20	20:26			11	2	0	0	0	0	0	0			SD TAKEN FOR AMP TRIPPED DUE TO RELAY MALOPERATION	NERPC/OP/TAC/2 0-21/443		SRMT
NER L209	MISA_MARIANI(OLD)	220			09/06/20	12:18	09/06/20	14:24			2	6	0	0	0	0	0	0				0-21/443		SRMT
					Sub Total -->						13	8	0	0	0	0	0	0				0-21/443	99.18	
NER L210	MISA_SAMAGURI# 1	34.439			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->						x	x	x	x	x	x	x			x	0-21/443	100	x	
NER L211	MISA_SAMAGURI# 2	34.439			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->						x	x	x	x	x	x	x			x	0-21/443	100	x	
NER L404	MISA-BALIPARA#2	95.407			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->																	0-21/443	100	
NER L206	MISA-KOPILI # 1	72.791			01/06/20	00:00	30/06/20	23:59			0	0	719	59	0	0	0	0			LINE PUT UNDER SD AFTER RUPTURE OF PENSTOCK NO 1	NERPC/OP/TAC/2 0-21/443	100	OMSU
					Sub Total -->						0	0	719	59	0	0	0	0				0-21/443	100	
NER L214	MISA-MARIANI(NEW)	222.682			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->						x	x	x	x	x	x	x			x	0-21/443	100	x	
NER L140	MOKUKCHUNG_MOKUK CHUNG#1	1.4			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->						x	x	x	x	x	x	x			x	0-21/443	100	x	
NER L141	MOKUKCHUNG_MOKUK HUNG#2	1.4			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->						x	x	x	x	x	x	x			x	0-21/443	100	x	
NER L144	NIRJULI_LEKHI(LILO)	5.5			10/06/20	10:50	10/06/20	11:30			0	0	0	40	0	0	0	0			TRIPPED DUE TO FAULT IN 132KV RANGANADI-CHIMPU (STATE FEEDERO	NERPC/OP/TAC/2 0-21/443		OMSU
NER L144	NIRJULI_LEKHI(LILO)	5.5			28/06/20	12:02	28/06/20	14:10			0	0	2	8	0	0	0	0			LINE H/T TO FACILITATE E/S/D AT LEKHI SS	NERPC/OP/TAC/2 0-21/443	100	OMSU
					Sub Total -->						0	0	2	48	0	0	0	0				0-21/443	100	
NER L409	PALLATANA-SURAJMANINAGAR # 1	37.2			22/06/20	10:21	22/06/20	13:29			0	0	3	8	0	0	0	0			LBB OPERATION IN STATE END BUS	NERPC/OP/TAC/2 0-21/443	100	SBBU
					Sub Total -->						0	0	3	8	0	0	0	0				0-21/443	100	
NER L410	PALLATANA-SURAJMANINAGAR# 2	37.2			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->						x	x	x	x	x	x	x			x	0-21/443	100	x	
NER L155	PARE(LILO)_RANGANADI	7.5			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->						x	x	x	x	x	x	x			x	0-21/443	100	x	
NER L129	RANGANADI-ZIRO	44.523			02/06/20	11:21	02/06/20	11:36			0	0	0	0	0	15	0	0			TRIPPED DUE TO UPROOTED BAMBOOS FALLING ON THE LINE FROM OUTSIDE LIEN CORRIDOR BETN LOC 42-43	NERPC/OP/TAC/2 0-21/443	100	LNCC
NER L129	RANGANADI-ZIRO	44.523			11/06/20	13:27	11/06/20	14:06			0	0	0	0	0	39	0	0			E/S/D TAKEN TO CLEAR BAMBOO WHICH CAME IN PROXIMITY TO Y-PHASE BETWEEN LOC. 4 AND 5.	NERPC/OP/TAC/2 0-21/443	100	LNCC
NER L129	RANGANADI-ZIRO	44.523			12/06/20	10:32	12/06/20	16:09			0	0	5	37	0	0	0	0			S/D TAKEN BY RANGANADI (NEEPCO)	NERPC/OP/TAC/2 0-21/443		OMSU
					Sub Total -->						0	0	5	37	0	54	0	0				0-21/443		
NER L101	RCN_AGARTALA# 1	8.384			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->						x	x	x	x	x	x	x			x	0-21/443	100	x	
NER L102	RCN_AGARTALA # 2	8.384			23/06/20	05:25	23/06/20	09:51			0	0	4	26	0	0	0	0			BUS RECTION SD TAKEN BY AGARTALA END	NERPC/OP/TAC/2 0-21/443	100	OMSU
					Sub Total -->						0	0	4	26	0	0	0	0				0-21/443	100	
NER L151	ROING-PASIGHAT	103			x	x	x	x			x	x	x	x	x	x	x			x	0-21/443	100	x	
					Sub Total -->						x	x	x	x	x	x	x			x	0-21/443	100	x	

Unique ID of transmission Element	Element Name	Description (Length/No./MVA/MVAR/MW/etc.)	Region	Type of failure	OUTAGE		RESTORATION		Details of Outage		Total outage in days (1)	DURATION OF OUTAGE ATTRIBUTABLE TO (in Hrs)						Restoration Time as per Regulation 5(b) (2)	Whether Restoration Time more than normative	Difference between Actual and Norm 1-2	Detailed Reason(s) for Outage	Outage Certifying Agency and Reference Document	% Availability as certified by certifying agency	
					Date	Time	Date	Time	No. of towers damaged	no. of insulator failed		ISTS License Hr	min	OTHERS Hr	min	System Constraints/ Natural calamity / MIBitancy Hr	min							
NER L159	ROING-TEZU	73			26/06/20	11:34	26/06/20	11:52				0	18	0	0	0	0	0	0		BAMBOO FROM OUSTIDE CORRIDOR CAME INTO PROXIMITY B/W LOC 73-74 DURING STRONG WINDS.	NERPC/OP/TAC/2 0-21/443	99.96	LNCC
					Sub Total -->							0	18	0	0	0	0	0	0					
NER L425	SILCHAR - MELRIAT	#1 143			20/06/20	18:54	20/06/20	19:13				0	18	0	0	0	0	0	0		RELAY MALOPERATION AT SILCHAR END	NERPC/OP/TAC/2 0-21/443	100	SRMT
NER L426	SILCHAR - MELRIAT#2	143			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER L423	SILCHAR_PKBARI	#1 127.9			22/06/20	16:46	22/06/20	17:04				0	18	0	0	0	0	0	0		FLASHOVER MARK FOUND IN R-PH CONDUCTOR BETWEEN LOC 226-227 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	99.96	OMST
NER L424	SILCHAR_PKBARI	#2 127.9			03/06/20	02:21	03/06/20	02:38				0	17	0	0	0	0	0	0		TRIPPED DUE TO MISCELLANEOUS REASON	NERPC/OP/TAC/2 0-21/443	100	OMST
					Sub Total -->							0	17	0	0	0	0	0	0					
NER L133	SILCHAR-BADARPUR-I#1	19,195			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER L134	SILCHAR-BADARPUR-II#2	19,195			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER L138	SILCHAR-HAILAKANDI	#1 17.3			03/06/20	09:26	03/06/20	17:29				8	3	0	0	0	0	0	0		SD AVALIED FOR CT TAN DELTA & RELAY TEST AT STATE END	NERPC/OP/TAC/2 0-21/443	100	OSPT
NER L138	SILCHAR-HAILAKANDI	#1 17.3			26/06/20	13:57	26/06/20	15:34				0	0	1	37	0	0	0	0		BUS SD TAKEN BY STATE AT HAILAKANDI SS	NERPC/OP/TAC/2 0-21/443	100	OMSU
					Sub Total -->							8	3	1	37	0	0	0	0					
NER L139	SILCHAR-HAILAKANDI	#2 17.3			02/06/20	06:37	02/06/20	06:49				0	0	0	0	0	12	0	0		BURNING MARKS FOUND IN EARTHWIRE VD AT LOC 99 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	100	LNCC
NER L139	SILCHAR-HAILAKANDI	#2 17.3			06/06/20	09:47	06/06/20	10:06				0	0	0	0	0	19	0	0		FLASHOVER MARK AT INSULATOR AT LOC 80 DUE TO LIGHTNING	NERPC/OP/TAC/2 0-21/443	100	LNCC
NER L139	SILCHAR-HAILAKANDI	#2 17.3			26/06/20	13:58	26/06/20	15:27				0	0	1	29	0	0	0	0		BUS SD TAKEN BY STATE AT HAILAKANDI SS	NERPC/OP/TAC/2 0-21/443	100	OMSU
					Sub Total -->							0	0	1	29	0	31	0	0					
NER L415	SILCHAR-IMPHAL	#1 174			22/06/20	08:38	22/06/20	08:44				0	6	0	0	0	0	0	0		TRIPPED DUE TO TRIPPING OF B/R AT IMPHAL	NERPC/OP/TAC/2 0-21/443	100	OMST
					Sub Total -->							0	6	0	0	0	0	0	0					
NER L416	SILCHAR-IMPHAL#2	174			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER L135	SILCHAR-SRIKONA-I#1	1,199			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER L136	SILCHAR-SRIKONA-II#2	1,199			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER L427	SURJAMANINAGAR - COMILLA#1	68			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER L428	SURJAMANINAGAR - COMILLA#2	68			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER L158	TEZU-NAMSAI	95.1			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER RBR6	BR_AIZWAL (20MVAR)	20			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER RBR3	BR_BALIPARA (50MVAR)#1	50			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER RBR17	BR_BALIPARA(125MVAR)	#3 125			08/06/20	11:05	08/06/20	19:08				0	0	0	0	0	0	8	3		SHUTDOWN TAKEN FOR COMMISSIONING OF NEW CSD	NERPC/OP/TAC/2 0-21/443	100	SCSD
NER RBR17	BR_BALIPARA(125MVAR)	#3 125			08/06/20	19:08	08/06/20	22:37				0	0	0	0	0	0	3	29		REACTOR KEPT OPEN AS PER NERLDC INSTRUCTION	NERPC/OP/TAC/2 0-21/443	100	SVRD
					Sub Total -->							0	0	0	0	0	0	11	32					
NER RBR8	BR_BALIPARA(80MVAR)# 2	80			x	x	x	x				x	x	x	x	x	x	x	x			NERPC/OP/TAC/2 0-21/443	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER RBR12	BR_B'CHARIALI(80MVAR) #1	80			x	x	x	x				x	x	x	x	x	x	x	x			V	100	x
					Sub Total -->							x	x	x	x	x	x	x	x					
NER RBR13	BR_B'CHARIALI(80MVAR) #2	80			x	x	x	x				x	x	x	x	x	x	x	x				100	x

Unique ID of transmission Element	Element Name	Description (Length/No./MVA/MVAR/MW/etc.)	Region	Type of failure	OUTAGE		RESTORATION		Details of Outage		Total outage in days (1)	DURATION OF OUTAGE ATTRIBUTABLE TO (in Hrs)				Restoration Time as per Regulation 5(b) (2)	Whether Restoration Time more than normative	Difference between Actual and Norm 1-2	Detailed Reason(s) for Outage	Outage Certifying Agency and Reference Document	% Availability as certified by certifying agency				
					Date	Time	Date	Time	No. of towers damaged	no. of insulator failed		ISTS License min	OTHERS Hr min	System Constraints/ Natural calamity/ MIBtancy Hr min	Deemed Available Hr										
					Sub Total -->																100				
NER RBR1	BR_BONGAIGAON (50MVAR) # 1	50			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR2	BR_BONGAIGAON (50MVAR) # 2	50			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR16	BR_BONGAIGAON(125MVAR)#5	125			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR7	BR_BONGAIGAON(80MVAR)#3	80			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR11	BR_BONGAIGAON(80MVAR)#4	80			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR20	BR_IMPHAL (80MVAR) #1	80			22/06/20	08:38	22/06/20	08:45			0	7	0	0	0	0	0								
NER RBR20	BR_IMPHAL (80MVAR) #1	80			29/06/20	20:25	29/06/20	23:53			0	0	0	0	0	0	3	28			H/T FOR VOLTAGE REGULATION				
NER RBR20	BR_IMPHAL (80MVAR) #1	80			29/06/20	20:25	29/06/20	23:53			0	0	0	0	0	0	3	28			H/T FOR VOLTAGE REGULATION				
NER RBR20	BR_IMPHAL (80MVAR) #1	80			30/06/20	17:06	30/06/20	23:59			0	0	0	0	0	0	6	53			H/T FOR VOLTAGE REGULATION VIDE CODE NO 1700				
					Sub Total -->						0	7	0	0	0	0	13	49							
NER RBR14	BR_IMPHAL(20MVAR)	20			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR5	BR_KUMARGHAT (20MVAR)	20			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR4	BR_MISA (50MVAR)	50			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR28	BR_MISA (80MVAR)	80			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR22	BR_MOKOKCHUNG(31.5MVAR)	31.5			05/06/20	16:55	05/06/20	19:58			3	3	0	0	0	0	0				E/S/D TAKEN FOR CHECKING OF DC EARTH FAULT IN BUS REACTOR.		99.58	OMST	
					Sub Total -->						3	3	0	0	0	0	0								
NER RBR15	BR_NEW MARIAN(20MVA)#1	20			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR18	BR_ROING(20MVAR)#1	20			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR21	BR_SILCHAR(125MVAR)	#3	125		01/06/20	19:22	01/06/20	21:37			2	15	0	0	0	0	0				BUCCHOLZ AND DIFFERENTIAL RELAY OPERATED			SRMT	
NER RBR21	BR_SILCHAR(125MVAR)	#3	125		06/06/20	10:37	06/06/20	11:52			1	15	0	0	0	0	0				TRIPPING OCCURRED DUE TO A SUSPECTED INTERMINENT FAULT OCCURRING IN THE CABLE CONNECTING THE BUCHHOLZ			OMST	
NER RBR21	BR_SILCHAR(125MVAR)	#3	125		12/06/20	11:02	12/06/20	16:31			5	29	0	0	0	0	0				S/D TAKEN FOR CHECKING OF CABLES (DIFFERENTIAL PROTECTION)			OMST	
NER RBR21	BR_SILCHAR(125MVAR)	#3	125		28/06/20	18:37	28/06/20	20:18			0	0	0	0	0	1	41				B/R H/T VIDE CODE 1463 FOR VOLTAGE REGULATION			SVRD	
					Sub Total -->						8	59	0	0	0	1	41								
NER RBR9	BR_SILCHAR(63MVAR)#1	63			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR10	BR_SILCHAR(63MVAR)#2	63			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR19	BR_TEZU(20 MVA)#1	20			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR25	LR_AZARA AT SILCHAR (63MVAR)	63			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR24	LR_BNC AT BALIPARA(63MVAR)#2	63			x	x	x	x			x	x	x	x	x	x	x				NERPC/OP/TAC/2 0-21/443			x	
					Sub Total -->																	NERPC/OP/TAC/2 0-21/443			x
NER RBR27	LR_PALLATANA - I AT SILCHAR(50MVAR)#1	50			x	x	x	x			x	x	x	x	x	x	x				NERPC/OP/TAC/2 0-21/443			x	
					Sub Total -->																	NERPC/OP/TAC/2 0-21/443			x
NER RBR23	LR_SUBANSIRI AT BNC(63MVAR)#1	63			x	x	x	x			x	x	x	x	x	x	x				100	x			
					Sub Total -->																	100			
NER RBR21	LR_BNC AT BALIPARA(50MVAR)	#1	#N/A		01/06/20	00:00	30/06/20	23:59			0	0	0	0	719	59	0	0			INTERNAL FAULT DETECTED IN WINDING DUE TO LIGHTNING DUE TO AMPHAN ON 23RD MAY			SNCC	
					Sub Total -->						0	0	0	0	719	59	0	0				100			
NER RBR29	BR_MEURIAT	#N/A	#N/A		06/06/20	08:25	06/06/20	15:13			6	48	0	0	0	0	0				S/D TAKEN FOR AMP OF BAY EQUIPMENTS.			OSPT	

Unique ID of transmission Element	Element Name	Description (Length/No./MVA/MVAr/MW(etc.))	Region	Type of failure	OUTAGE		RESTORATION		Details of Outage		Total outage in days (1)	DURATION OF OUTAGE ATTRIBUTABLE TO (in Hrs)								Restoration Time as per Regulation 5(b) (2)	Whether Restoration Time more than normative	Difference between Actual and Norm 1-2	Detailed Reason(s) for Outage	Outage Certifying Agency and Reference Document	% Availability as certified by certifying agency									
					Date	Time	Date	Time	No. of towers damaged	no. of insulator failed		ISTS License Hr	min	OTHERS Hr	min	System Constraints/ Natural calamity / MIBitancy Hr	min	Deemed Available Hr	min															
NER TICT25	ICT_NIRJULI(50MVA)#2	50			x		x		x			x	x	x	x	x	x					x	0-21/443	100	x									
Sub Total -->																																		
NER TICT2	ICT_SALAKATI (50 MVA)#1	50			x		x		x			x	x	x	x	x	x					x		100	x									
Sub Total -->																																		
NER TICT21	ICT_SALAKATI(50MVA)	#2	50		01/06/20	09:33	01/06/20	18:31				0	0	0	0	0	0	8	58				SD TAKEN FOR NEW REF RELAY RETROFITTING	100	SCSD									
Sub Total -->																			0	0	0	0	0	0	8	58								
NER TICT11	ICT_SILCHAR(200MVA)#1	200			x		x		x			x	x	x	x	x	x					x		100	x									
Sub Total -->																																		
NER TICT12	ICT_SILCHAR(200MVA)#2	200			x		x		x			x	x	x	x	x	x					x		100	x									
Sub Total -->																																		
NER TICT27	ICT_SILCHAR(315MVA)#3	315			x		x		x			x	x	x	x	x	x					x		100	x									
Sub Total -->																																		
NER TICT7	ICT_ZIRO (15MVA)	15			x		x		x			x	x	x	x	x	x					x		100	x									
Sub Total -->																																		
NER TICT31	ICT-BONGAIGAON(315MVA)#2	315			x		x		x			x	x	x	x	x	x					x		100	x									
Sub Total -->																																		