

<b>RTI REQUEST DETAILS</b>	
<b>Registration No. :</b> PGCIL/R/E/24/00297	<b>Date of Receipt :</b> 09/06/2024
<b>Type of Receipt :</b> Online Receipt	<b>Language of Request :</b> English
<b>Name :</b> KALPATARU MAJHI	<b>Gender :</b> Male
<b>Address :</b> At- Raulahaja, Po/Ps- Nirakarpur, Dist- Khordha, Pin:752019	
<b>State :</b> Odisha	<b>Country :</b> India
<b>Phone No. :</b> +91-9040756454	<b>Mobile No. :</b> +91-9040756454
<b>Email :</b> kalpatarumajhi1963@gmail.com	
<b>Status(Rural/Urban) :</b> Rural	<b>Education Status :</b> Graduate
<b>Is Requester Below Poverty Line ? :</b> No	<b>Citizenship Status :</b> Indian
<b>Amount Paid :</b> 10 )	<b>Mode of Payment :</b> Payment Gateway
<b>Does it concern the life or Liberty of a Person ? :</b> No(Normal)	<b>Request Pertains to :</b>
<b>Information Sought :</b>	<p>I am Kalpataru Majhi            Electricity Consumer number - 080035396425, Division - Khurda            KED No.- 5001429351 Section - Nirakarpur, Raulahaja            Sub: In our Electricity Section Nirakarpur Area, most of the time we the consumers face load shedding &amp; low voltage problem. Due to very low voltage, cooler, submersible pump of 1 hp refrigerator, ceiling fans &amp; grinders are not being taken on service, Without strong wind flow or rainfall power supply is being stopped without prior information, many times power cut-off is done.</p> <ol style="list-style-type: none"> <li>1. I want to know what are the causes of above problem.</li> <li>2. What to be done to solve above problems.</li> <li>3. how much time you wil take to solve the problems.</li> </ol>
<input type="button" value="Print"/> <input type="button" value="Save"/> <input type="button" value="Close"/>	