


From

Sanjeev Kumar
45 Ranjit Bagh,
Opposite Modi Mandir,
Patiala- 147001



To

CPIO WRLDC,
Mumbai

No SK RTI

Dated: 23 April 2014

Sub: Application under RTI Act 2005

It is requested that the following information may please be supplied under RTI Act .

DESCRIPTION


On 22 April 2014, the DC of Sasan was reduced from 1861.2 to 568 MW. It appears that there was outage of 2 nos Units. Outage of unit is a reportable event under IEGC.

INFORMATION REQUESTED TO BE SUPPLIED.

- 1 PI supply copy of messages from SPL to WRLDC on 22 Apr 2014 on the subject of outage of Sasan units on 22 Apr 2014.
- 2 PI supply copy of all messages from SPL to WRLDC on 22-4-2014 for revision of DC of Sasan for 22-4-2014.

RTI fee of Rs10 is encl


Sanjeev Kumar





पावरग्रिड



पावर सिस्टम ऑपरेशन कारपोरेशन लिमिटेड
(पावरग्रिड की पूर्ण स्वामित्व प्राप्त सहायक कंपनी)
POWER SYSTEM OPERATION CORPORATION LIMITED
(A Wholly owned subsidiary of POWERGRID)



पश्चिम क्षेत्रीय भार प्रेषण केन्द्र

एफ-3, सेन्ट्रल रोड, एम्.आई.डी.सी. एरिया, मरोल, अन्धेरी (पूर्व), मुंबई - 400 093.
दूरभाष : 022-28202691 • फैक्स : 022-28235434, 28202630 • ई-मेल : wrldc@posoco.in

WESTERN REGIONAL LOAD DESPATCH CENTRE

F-3, MIDC Area, Marol, Andheri (East), Mumbai - 400 093.

Phone : 022-28202691 • Fax : 022- 28235434, 28202630 • E-mail : wrldc@posoco.in

संदर्भ संख्या, Ref. No.

Ref: WRLDC/SO-I/RTI/309/14/ 642

Date: 15.05.2014

TO

Sanjeev Kumar,
45,Ranjit Bagh,Opposite Modi Mandir
Patiala,147001

Subject: Information sought under RTI Act, 2005.

Dear Sir,

This is in reference to your letter dated 26th April, 2014 received in this office on 30th April,2014 regarding the information on forced outages of Sasan units for the period of commercial operation of each units upto 30.04.14.

The point-wise reply of your query as provided by concerned department is as mentioned below:

क्रम संख्या	आवेदन में मांगी गई जानकारी	संबन्धित जवाब
1.	Please give list of forced outages/trippings of Sasan unit 3 for the period 16 th august 2013 upto 30 th Apr 2014, giving the date ,time,and cause/reason for tripping. May be supplied in format as Sr no.,date,time cause of outage of unit 3.	List is enclosed
2.	Information regarding unit-2 may please be supplied similiary for period 28 th Jan 2014 upto 30.04.2014.	List is enclosed
3.	Information regarding Unit-4 may please be supplied similiary for period 12 th Apr 2014 upto 30.04.14	List is enclosed

Thanking you.

(V K Shrivastava)

AGM & CPIO,

CC: GM & AA, WRLDC, Mumbai: - for kind information please.

स्वहित एवं राष्ट्र हित में ऊर्जा बचायें

Save Energy for Benefit of Self and Nation

पंजीकृत कार्यालय: बी-9, कुतब इंस्टीट्यूशनल एरिया, कटवारिया नगर, नई दिल्ली - 110 016. दूरभाष : 26560121 फैक्स : 26560039.
Registered Office : B-9, Qutab Institutional Area, Katwaria Sarai, New Delhi - 110 016. Tel.: 26560121 Fax : 26560039.

o/c

DETAILS OF OUTAGE/ TRIPPING OF SASAN UNIT -3

UNIT NO.	RELIANCE	OUTAGE TIME	RESTORATION TIME	CAUSE OF OUTAGE/TRIPPING
SASAN-3	ISGS	23:57	5:10	FLASHING OVER AT GT
SASAN-3	ISGS	14:46	21:49	BFP PROBLEM
SASAN-3	ISGS	18:32	23:00	COAL MILL PROBLEM
SASAN-3	ISGS	3:30	17:35	GEN. PROTN OPTD.
SASAN-3	ISGS	11:34	0:01	GENERATOR PROTCN OPTD
SASAN-3	ISGS	11:49	16:19	TRIPPED ON TURBINE PROTECTION
SASAN-3	ISGS	7:41	2:28	ELECTRICAL FAULT
SASAN-3	ISGS	3:32	9:39	GT DIFFERENCIAL PROT OPTD
SASAN-3	ISGS	17:32	3:36	UAT-B BUCCHOLZ RELAY OPTD.
SASAN-3	ISGS	10:18	14:45	CONV BELT PROBLEM
SASAN-3	ISGS	10:30	1:25	TRIPPED ON TURBINE PROTECTION
SASAN-3	ISGS	2:00	5:44	CWP PROBLEM
SASAN-3	ISGS	17:00	9:45	COAL BUNKERING PROBLEM
SASAN-3	ISGS	20:36	11:03	COAL MILL TRIPPED /TG LUB OIL SYSTEM
SASAN-3	ISGS	0:35	9:02	CLASS A ACT
SASAN-3	ISGS	21:22	0:30	COAL HANDLING PROBLEM
SASAN-3	ISGS	19:43	3:31	REHEATER TEMP HIGH
SASAN-3	ISGS	3:09	12:44	GEN DIFFERENTIAL PROTN OPTD.
SASAN-3	ISGS	11:10	19:43	TRIPPING OF AUX UNIT SWITCH BOARD
SASAN-3	ISGS	19:34	5:57	BOILER FLAME FAILURE

DETAILS OF OUTAGE/ TRIPPING OF SASAN UNIT -2

SASAN-2	2	ISGS	RELIANCE	660	OUTAGE TIME		RESTORATION TIME	CAUSE OF OUTAGE/TRIPPING
SASAN-2	2	ISGS	RELIANCE	660			29-Jan-14 4:12	FIRST TIME SYNCHRONISED
SASAN-2	2	ISGS	RELIANCE	660	17:16	29-Jan-14	1:51	PA FAN PROBLEM
SASAN-2	2	ISGS	RELIANCE	660	9:01	5-Feb-14	14:33	BOILER PRESSURE HIGH
SASAN-2	2	ISGS	RELIANCE	660	17:12	6-Feb-14	9:55	GEN. DIFFERENTIAL PROTN. OPTD
SASAN-2	2	ISGS	RELIANCE	660	6:44	14-Feb-14	12:24	GEN. PROTN. OPTD
SASAN-2	2	ISGS	RELIANCE	660	2:05	16-Feb-14	16:50	PROBLEM IN ASH HANDLING
SASAN-2	2	ISGS	RELIANCE	660	9:20	1-Mar-14	6:37	AIR PREHEATER PROBLEM
SASAN-2	2	ISGS	RELIANCE	660	11:10	14-Mar-14	22:36	TRIPPING OF AUX UNIT SWITCH BOARD
SASAN-2	2	ISGS	RELIANCE	660	23:34	7-Apr-14	0:32	GT TRANSFORMER TRIPPED
SASAN-2	2	ISGS	RELIANCE	660	19:16	22-Apr-14	6:05	WATER LEAKAGE BFP RC LINE NRV
SASAN-2	2	ISGS	RELIANCE	660	20:14	28-Apr-14	3:55	AIR PREHEATER PROBLEM
SASAN-2	2	ISGS	RELIANCE	660	4:40	28-Apr-14	5:40	BOILER TRIP

DETAILS OF OUTAGE/ TRIPPING OF SASAN UNIT -4

SASAN-4	4	ISGS	RELIANCE	660	9:20	13-Apr-14	15:00	13-Apr-14	BTL
SASAN-4	4	ISGS	RELIANCE	660	23:27	13-Apr-14	6:11	14-Apr-14	Feed Water Level Low
SASAN-4	4	ISGS	RELIANCE	660	13:45	22-Apr-14	23:19	23-Apr-14	FEED WATER PUMP PROB.
SASAN-4	4	ISGS	RELIANCE	660	3:49	24-Apr-14	14:21	24-Apr-14	GT Y PH LA BURST
SASAN-2	2	ISGS	REL	660	20:14	28-Apr-14	3:55	7-May-14	AIR PRE HEATER PROBLEM