From: Mr. Rabindranath Dasmahapatra

Shop No. 51, Maruti Paradise, Sec - 15, Plot No. 92-95,

CBD Belapur, Navi Mumbai - 400 614.

Date: 06.07.2015

To, DGM (PESM) & CPIO Power Grid Corporation of India Limited. Dongtieh, Lower Nongrah, Lapalang, Shillong – 793006.



Dear Sir,

Subject: Information sought by us is not specific.

Ref. no.: 1. RTI/02/08/11/12/PGI

2. Our RTI application dated 03.02.2015

3. Your reply letter dated 25.02.2015 vide ref. no. NESH/PESM/RTI/1117/345

With reference to the above, vide question no. 4, 5, 6 and 8 we had asked you to furnish details

But the answer received is highly unsatisfactory and the reply is copy of one statement only.

of the works carried out for the tendered work in question.

But the answer received is highly unsatisfactory and While page no. 2 & 3 of the Annexure sent by you subject mention on both document are different.

The Schedule and your statements clearly indicates on the 12 nos. of pedestals in 3 nos. of well foundations of B In view of the above, kindly furnish specific answer to (1) Whether the work awarded to M/S DYNASOUR While page no. 2 & 3 of the Annexure sent by you are ridiculous and arouses suspicion as the

The Schedule and your statements clearly indicates that no underwater repairs are carried out on the 12 nos. of pedestals in 3 nos. of well foundations of Brahmaputra river.

In view of the above, kindly furnish specific answer to my query.

- (1) Whether the work awarded to M/S DYNASOURE CONCRETE TREATMENT PVT. LTD. Under Work order No.: NESH/CSM/O&M/1500-06/LOA/1313 Dated 23.09.2009 involved any underwater repair using epoxy mortar, epoxy concrete etc? (Give answer Yes or No)
- (2) The contention of Schedule of the work is only surface repairs. There is no indication / specification that underwater repairs are to be executed, clearly state that what was the scope of work? Whether it was underwater repair or surface repair? Please specify.
- (3) If any underwater repair are carried out what is the percentage of underwater repair carried out with respect to the total contract value.

Thank you

Signature of applicant

POWER GRID CORPORATION OF INDIA LIMITED

(A Government of India Enterprise)

ise) पावरग्रिड

डोंगटिय, लोवर नोंग्राह, लापालांग, शिलांग दू 7793006 (मेघालय)

दुरभाषः :0364द्ध 2536562, फैक्सः 2536387

Dongtieh, Lower Nongrah, Lapalang, Shillong – 7793006 (Meghalaya) Telephone: (0364) 2536562, Fax: 2536387

उत्तर पूर्वी क्षेत्र पारेषण प्रणाली/NORTH EASTERN REGION TRANSMISSION SYSTEM

संदर्भ संख्या / Ref No: NESH/PESM/RTI/1117/ 39

दिनांक / Date: 05.08.2015

To:

Mr. Rabindranath Dasmahapatra, Shop-51, Maruti Paradise, Sector-15, CBD Belapur, Navi Mumbai-400614, Maharashtra.

Sub: Reply to your RTI Query vide application dated 06.07.2015, received on 22.07.2015.

Sir,

1.0 This is in reference to your application dated 06.07.15 under RTI Act 2005, received on 22.07.2015.

2.0 As per information received from concerned site, the information against your queries pertaining to

POWERGRID, North Eastern Region are as follows:

Sl. No.	Query	Information
(1)	Whether the work awarded to M/s DYNASOURE CONCRETE TREATMENT PVT. LTD. Under work order No.: NESH/CSM/O&M/1500-06/LOA /1313, Dated 23.09.2009 involved any underwater repair using epoxy mortar, epoxy concrete etc.? (give answer Yes or No)	No under water repair was involved.
(2)	The contention of schedule of the work is only surface repairs. There is no indication / specification that underwater repairs are to be executed, clearly state that what was the scope of work? Whether it was underwater repair or surface repair? Please specify.	As per schedule of work against the LOA: NESH/CSM/O&M/1500-06/LOA/1313, Dated 23.09.2009, there is no mention of underwater works.
(3)	If any underwater repair are carried out what is the percentage of underwater repair carried out with respect to the total contract value.	Not Applicable.

3.0 Kindly acknowledge receipt of this letter.

90

Thanking you,

प्रतिलिपि (NIO):

1. उप महाप्रबंधक (सतर्कता), उप्क्षेपाप्र, शिलांग

उप महाप्रबंधक

(के. लो. सू. अधिकारी)