

**RTI REQUEST DETAILS**

**Registration No. :** PGCIL/R /2017/50236 **Date of Receipt :** 12/04/2017  
**Type of Receipt :** Online Receipt **Language of Request :** English  
**Name :** Mohit Singh **Gender :** Male  
**Address :** Vill-Bhikhepur, post-Bhikhepur, Dist- Auraiya, Pin:206129  
**State :** Uttar Pradesh **Country :** India  
**Phone No. :** Details not provided **Mobile No. :** +91-9761170250  
**Email :** mo.sin2k2@gmail.com  
**Status(Rural/Urban) :** Rural **Education Status :** Above Graduate  
**Is Requester Below Poverty Line ? :** No **Citizenship Status :** Indian  
**Amount Paid :** 10 ) **Mode of Payment :** Payment Gateway

**Request Pertains to :****Information Sought :**

- 1- Kindly Provide me the guide lines for payment of compensation towards damage in regards to tower base area (Between four legs) , ROW corridor and crop and tree damage due to laying of 400kV/500kV/765kV transmission line in India.
- 2- How and when the fixed compensation amount will be received by the Land lord.
- 3- What the Ministry of power policies regarding the fatal side effects of the transmission lines on organisms and vegetation.
- 4- Kindly provide detailed information of compensation made by ministry of power towards -
  - (a) Tower base area (between four legs) impacted severely due to installation of tower/pylon structure.
  - (b) Diminution of land value in the width of right of way corridor due to laying of transmission line.
  - (c) Crop and tree damage.
 in the year 2016-17

Print Save Close

2nd 12/4  
 → Lm (CP) / F-2  
 12/4  
 → Lm (CP) / m (CP)