

RTI REQUEST DETAILS

| | | | |
|--|---|------------------------------|-----------------|
| Registration No. : | PGCIL/R/2019/50274 | Date of Receipt : | 12/06/2019 |
| Type of Receipt : | Online Receipt | Language of Request : | English |
| Name : | Meena Choudhary | Gender : | Female |
| Address : | Ram Ratan Lane, Kali Mandir, Adampur, Bhagalpur, Bihar, Pin:812001 | | |
| State : | Bihar | Country : | India |
| Phone No. : | +91-7484914004 | Mobile No. : | +91-7484914004 |
| Email : | ramchandra_pg@yahoo.com | | |
| Status(Rural/Urban) : | Urban | Education Status : | Graduate |
| Is Requester Below Poverty Line ? : | No | Citizenship Status | Indian |
| Amount Paid : | 10) | Mode of Payment | Payment Gateway |
| Request Pertains to : | | | |
| Information Sought : | <p>Following information pertaining to collapse of Pile Foundation Towers of POWERGRID Transmission Lines in Eastern Region-1 may kindly be furnished for transmission lines commissioned in last 11 years from the date of submission of this application.</p> <p>1. Following set of information for EACH partial or full Failure / Collapse / Damage of Pile Foundation Tower of POWERGRID Transmission Lines in Eastern Region-1 for transmission lines commissioned in last 11 years from the date of submission of this application.</p> <p>A. Name of Transmission Lines, Location Number, Tower Number, Block Name, District Name</p> <p>a) Date of completion of such Pile Foundation Tower b) Name of Engineer In-Charge, as per LoA, during its construction c) Name of Regional Project Head during its construction d) Name of Regional Head during its construction e) Date of its partial or full Failure / Collapse f) Name of O&M Site In-Charge at the time of its partial or full Failure / Collapse g) Name of Regional AM Head at the time of its partial or full Failure / Collapse h) Name of Regional Head at the time of its partial or full Failure / Collapse i) Date of LoA for restoration Work j) Name of O&M Site In-Charge at the time of issuance of LoA k) Name of Engineer In-Charge for restoration work, as per LoA l) Date of full restoration of the line, of which the tower was a part m) Cost of such Restoration Works n) Revenue Loss to POWERGRID due to such partial / full failure, collapse, damage or outage o) Incentive Loss to POWERGRID due to such partial / full failure, collapse, damage or outage p) Copy of all internal/external/vigilance enquiry reports</p> | | |

- q) Copy of all kinds of audit observations and compliance reports
- r) Copy of documents pertaining to official communications on record (including electronic communication) regarding memo, warning, minor penalty, major penalty, any other punishment issued / given to any officer of POWERGRID. The present designation of such officer (s) along with his present location, department, work responsibility etc. should also be furnished.

Separate set of Information in above format for all such cases in ER-1 is to be furnished.